

300UX6 & PFAFF 5625

Images may include options. Las imágenes pueden incluir opciones.



Technical Information

OPTIONS

Parts:	Needle	SN62x5924
	Feed Dog	9105949305
	Throat Plate	91-15089-05
	Lifting Presser Foot.....	91-149-219-91
	Alternating Presser Foot....	91-149-220-91

Información Técnica

OPCIONES

Partes:	Aguja	SN62x5924
	Prénsatelas.....	9105949305
	Placa de agujas.....	91-15089-05
	Prénsatelas elevador.....	91-149-219-91
	Pie alternante	91-149-220-91

PFAFF 5625

Single Needle, Walking Foot, Two Thread, Chainstitch Machine

- Very high stitch quality for top stitching and decorative seams
- High traction due to unison feed (Bottom feed and alternating top and needle feed)
- Simple threading, owing to swing-out loopers
- All threading points are accessible from the front of the machine
- Enclosed oiling system with auto lubrication

Máquina de Una Aguja, Pies Alternantes, Cadeneta de dos hilos

- *Muy alta calidad de puntada para pespunte y costuras decorativas*
- *Alta tracción debido a la alimentación al unísono (Alimentación inferior y superior alternante y por aguja)*
- *Enhebrado simple, debido al movimiento retráctil de los loopers*
- *Todos los puntos de enhebrado son accesibles desde la parte frontal de la máquina*
- *Sistema de lubricación automático de depósito sellado*

SPECIFICATIONS / ESPECIFICACIONES	
Max sewing speed (rpm) / Max velocidad de costura (rpm)	5000
Max stitch length (spi) / Max longitud de puntada (spi)	8.5
Needle system / Sistema de aguja	SN62X5924
Needle size / Tamaño de aguja	24/180
Weight of material / Tipo de material	MEDIUM / HEAVY
Max presser footlift (inch) / Max elevación del prénsatelas (pulgadas)	14 mm



www.atlatt.com • sales@atlatt.com

PATENTS: Our equipment may be covered by one or more patents. Please go to the following web page for an up-to-date patent list: www.atlatt.com/patents

© 2017 Atlanta Attachment Co.

17014013117



Atlanta Attachment Company

362 Industrial Park Drive
Lawrenceville, GA 30046

+1 (770) 963-7369 • FAX +1 (770) 963-7641

The Company that
Sudden Service®
built