



## Adjustable Gathering Workstation

- Gathers work piece for added fullness when going around interior contours
- Gathering turns on/off with the press of a knee switch
- All feed wear components run in constant oil bath for greater machine/component longevity
- Amount of gather is easily adjusted without tools