



PLEASE NOTE:
THIS WIRING DIAGRAM TO ONLY
BE USED WITH PANASONIC FP
SIGMA PLC (FPG-C32TH)

CUT SENSOR
BRN = RED CABLE SIDE
BLU = BLK CABLE SIDE
BLK = WHT
X = GRN



XXX-XX

NO.	REVISION	DATE	DR.	CK.	QTY. REQD.	ITEM NO.	DESCRIPTION	PART NO. STOCK SIZE
2	080-11	6-13	TM					
1	004-11	1-12	TM					
FINISH					DEFAULTS			
PLAIN/CLEAN					COUNTERSINKS:			
BURR BENCH					.02			
BLACKOXIDE					SHEET METAL FAB			
HEAT TREAT					.X = ± .100			
SAND BLAST					.XX = ± .050			
BUFF					.XXX = ± .015			
PAINT					.XXXX = AS SPECIFIED			
CLEAR CHROMATE					SCALE			
TIMESAVE					DATE: 10-20-10			
OIL					DWG SIZE B			
ATLANTA ATTACHMENT COMPANY							PART NO. 1393E-WD4	
NAME DIAGRAM, WIRING, PAGE 4							DRAWING NO. 125887B	
2nd DES. PLC INPUT, 1393E							REV 3	
MATERIAL N/A								
NEXT ASSY 11393E								
DES. BY JSK								
DR. BY JSK								
CK. BY								

The materials contained herein are confidential and proprietary information of Atlanta Attachment Company. In addition to any confidentiality and non-disclosure obligations that currently exist between you and Atlanta Attachment Company, your use of these materials serves as an acknowledgment of the confidential and proprietary nature of these materials and your duty not to make any unauthorized use or disclosure of these materials.

